## HISTORIC AMERICAN ENGINEERING RECORD

## Index to Photographs

E and T. Fairbanks and Co. Two-Story Covered Bridge St. Johnsbury, Vt. Caledonia County Vermont HAER No. VT-1-A

Documentation:

1 article (3 pages)

15 photographs (August 1969)

Photographer: Jack Boucher

VT-1-A-1 Along river to bridge, north side.

VT-1-A-2 Detail typical gothic window, south side of bridge.

VT-1-A-3 Detail of south exterior side of bridge from west.

VT-1-A-4 Detail of north side of bridge showing some of cable bracing beneath.

VT-1-A-5 North side of bridge from building on east end.

VT-1-A-6 North side of the bridge, from old building on west from 2nd floor.

VT-I-A-7 From west, past loading platform to bridge showing gothic windows on south side.

VT-1-A-8 Laminated arch, 2nd floor bridge; view is south.

VT-1-A-9 Truss bracing, inside laminated arch, 1st floor; view is south.

VT-1-A-10 View to southeast, showing trusses and 1st floor section of laminated arch in bridge.

VT-1-A-11 Detail of section of laminated arch, 1st floor, west end.

VT-1-A-12 Detail of trusses between laminated wooden arch in bridge.

VT-1-A-13 General view of trusses/bracing, 2nd floor, north exterior wall inside.

VT-1-A-14 Detail of bracing near base of laminated wood arch, 2nd floor of bridge.

VT-1-A-15 Detail of section of laminated wood arch west end of 2nd floor.